

SATRONICS SOLDER IRON TIPS

FOR SOLDER IRON :

ZD30C/30 / 40W = ZDC1-X

ZD60W = ZDC2-X

ZD99 TIP TYPE = ZDC2-X



" C " TYPE TIP

HI QUALITY LONG LIFE TIP .



Material ,: Pure Copper , plated with iron alloy and Tin plated tip .
Tip front size as per drawing .



TIP: (C1)



TIP: (C2)



FOR SOLDER IRON :

ZD30CN = TIP TYPE = N1-x



ZD929C = TIP TYPE N1-X6

ZD932 = TIP TYPE = N1-X6

" N " TYPE TIP

HI QUALITY LONG LIFE TIP .

Material : Pure Copper , plated with iron alloy and Tin plated tip .
Tip front size as per drawing .



SATRONICS SOLDER IRON TIPS

FOR SOLDER IRON

ZD401

QK3002

ZDB1-X = 30/40 W , ZDB2-X = 60W


ZDB3-X = 80W , ZDB4-X = 100W

" B " TYPE TIP


HI QUALITY LONG LIFE TIP .

Material ,: Pure Copper , plated
with iron alloy and Tin plated tip .


Tip front size as per drawing .




B1-1




B2-1




B3-1




B1-2




B2-2




B3-2



B1-3



B2-3



B3-3